

FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV																																						
<p><u>Ladder symbol</u></p> <table border="1" style="margin-left: auto; margin-right: auto;"> <tr> <td rowspan="2" style="text-align: right; padding-right: 5px;">Operate</td> <td style="padding: 2px;">R0</td> <td style="padding: 2px;">IR</td> <td style="padding: 2px;">ROR</td> <td style="padding: 2px;">DR</td> <td style="padding: 2px;">K</td> </tr> <tr> <td style="padding: 2px;">R3839</td> <td style="padding: 2px;">R3840</td> <td style="padding: 2px;">R5000</td> <td style="padding: 2px;">D0</td> <td style="padding: 2px;"></td> </tr> <tr> <td style="padding: 2px;">Md</td> <td style="padding: 2px;"></td> <td style="padding: 2px;"></td> <td style="padding: 2px;"></td> <td style="padding: 2px;">0~3</td> </tr> <tr> <td style="padding: 2px;">S</td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> </tr> <tr> <td style="padding: 2px;">Ts</td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> </tr> <tr> <td style="padding: 2px;">D</td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> <td style="padding: 2px;"><input checked="" type="radio"/>*</td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> </tr> <tr> <td style="padding: 2px;">L</td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;"><input type="radio"/></td> <td style="padding: 2px;">1~64</td> </tr> </table>	Operate	R0	IR	ROR	DR	K	R3839	R3840	R5000	D0		Md				0~3	S	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>		Ts	<input type="radio"/>		<input type="radio"/>	<input type="radio"/>		D	<input type="radio"/>		<input checked="" type="radio"/> *	<input type="radio"/>		L	<input type="radio"/>		<input type="radio"/>	<input type="radio"/>	1~64
Operate		R0	IR	ROR	DR	K																																		
	R3839	R3840	R5000	D0																																				
Md				0~3																																				
S	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>	<input type="radio"/>																																				
Ts	<input type="radio"/>		<input type="radio"/>	<input type="radio"/>																																				
D	<input type="radio"/>		<input checked="" type="radio"/> *	<input type="radio"/>																																				
L	<input type="radio"/>		<input type="radio"/>	<input type="radio"/>	1~64																																			

- When the analog input module being used for the analog measurement, the raw reading value of the analog input can be converted into the engineering range through this instruction for display or for proceeding control operation.
- For process measurement calibration, making the linear conversion for the engineering process variable, which the measurement value from the PLC's can be corrected by the value from the standard meter's through this instruction.
- When execution control "EN"=1 or from 0→1 (P instruction), this instruction will perform the linear conversion operation according to the mode selection, where S is the starting address of the source data, Ts is the starting address of the conversion parameter table, D is the starting address to store the converted result, and L is the quantity of conversion entry.
- There are two expressions to meet the suitable application:

Expression 1 : Two points calibration method


Fill the conversion parameter table with the low value of measurement(VML), high value of measurement(VMH), and the corresponding low value of standard (VSL), high value of standard(VSH); the converted result(Dn) will be generated from the source data(Sn) through the formula shown below:

$$A = (VSL - VSH) / (VML - VMH) \times 10000$$

$$B = VSL - (VML \times A / 10000)$$

$$Dn = (Sn \times A / 10000) + B$$

- The range of operands VSL, VSH, VML, VMH, Sn and Dn are between -32768 ~ 32767
- For analog input scaling, where VML=Minimum of analog input VMH=Maximum of analog input VSL=Minimum of engineering range VSH=Maximum of engineering range



Advanced Function Instruction


FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV
Expression 2 : Multiplicator + Offset method		
<p>Fill the conversion parameter table with the values of multiplier(A), divisor(B) and offset(C); The converted result(Dn) will be generated from the source data(Sn) through the formula shown below:</p> $Dn = [(Sn \times A) / B] + C$ <p>The range of each operand as below:</p> <p>A = 1 ~ 65535 B = 1 ~ 65535 C = -32768 ~ 32767 Sn = 0 ~ 65535 Dn = -32768 ~ 32767</p>		

Description of operation mode :


- When $Md = 0$, the linear conversion works by expression 1, and all source data share the same parameters VML、VMH、VSL and VSH for conversion.
- When $Md = 1$, the linear conversion works by expression 1, and each source data has the independent corresponding parameters VML、VMH、VSL、VSH for conversion; if there are N entries of source data, the conversion parameter table should have N groups of VML、VMH、VSL、VSH for working, there are $N \times 4$ registers in the conversion parameter table.
- When $Md = 2$, the linear conversion works by expression 2, and all source data share the same parameters A、B and C for conversion.
- When $Md = 3$, the linear conversion works by expression 2, and each source data has the independent corresponding parameters A、B、C for conversion; if there are N entries of source data, the conversion parameter table should have N groups of A、B、C for working, there are $N \times 3$ registers in the conversion parameter table.

FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV
-----------------	-----------------------------	-----------------

Example program 1 : Mode 0 of linear conversion




Description: When M0 = 1, it will perform the mode 0 operation of linear conversion, where R100 is the starting address of the source data, R1000 is the starting address of the table of the conversion parameters VML、VMH、VSL、VSH, the quantity is 6, and R2000~R2005 will store the converted results.



Advanced Function Instruction

FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV
-----------------	-----------------------------	-----------------

Example program 2 : Mode 1 of linear conversion



Description : When M0 = 1, it will perform the mode 1 operation of linear conversion, where R100 is the starting address of the source data, R1000 is the starting address of the table of the conversion parameters VML、VMH、VSL、VSH, the quantity is 3, and R2000~R2002 will store the converted results.


Ts	
R1000	282
R1001	3530
R1002	260
R1003	3650
R1004	-52
R1005	1208
R1006	-38
R1007	1101
R1008	235
R1009	4563
R1010	264
R1011	4588

S	D
R100 282	R2000 260
R101 1208	R2001 1100
R102 2399	R2002 2426

Advanced Function Instruction

FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV
------------------------	-------------------------------------	------------------------

Example program 3 : Mode 2 of linear conversion



Description : When M0 = 1, it will perform the mode 2 operation of linear conversion, where R100 is the starting address of the source data, R1000 is the starting address of the table of the conversion parameters A、B、C, the quantity is 6, and R2000~R2005 will store the converted results.


Ts		A
R1000	985	A
R1001	1000	B
R1002	22	C
S		D
R100	1000	R2000 1005
R101	2345	R2001 2329
R102	3560	R2002 3526
R103	401	R2003 414
R104	568	R2004 579
R105	2680	R2005 2659



Advanced Function Instruction

FUN33 P LCNV	Linear Conversion (LCNV)	FUN33 P LCNV
-----------------	-----------------------------	-----------------

Example program 4 : Mode 3 of linear conversion



Description : When M0 = 1, it will perform the mode 3 operation of linear conversion, where R100 is the starting address of the source data, R1000 is the starting address of the table of the conversion parameters A、B、C, the quantity is 4, and R2000~R2003 will store the converted results.

Ts	
R1000	5000
R1001	16380
R1002	0
R1003	10000
R1004	16383
R1005	0
R1006	2200
R1007	16380
R1008	-200
R1009	1600
R1010	16383
R1011	-100

S	D
R100	8192
R101	16383
R102	8190
R103	0
⇒	
	R2000 2500
	R2001 10000
	R2002 900
	R2003 -100