



Updating of FBs OS V4.45

09/01/2006

- Modify the multi-axis motion instruction FUN147(MHSPO) to get correct current value of pulse for the active axes
- Remove the detection for system error code 11

.