

- Support floating point instructions FUN200 ~ FUN213
- Revise the hex-key input (FUN77) instruction
- Revise the write (FUN161,WR-DP) instruction for ROM PACK manipulation
- Revise the read (FUN162,RD-DP) instruction for ROM PACK manipulation
- While working in RUN mode, the RUN indicator of the PLC main unit flickers in 10 Hz frequency (Fast blink).
- The manufacturing default is 3 mS as the communication reply delay time
R4040=0303H ; the defaults are 3 mS for Port 0 & Port 1 reply delay time
R4041=0303H ; the defaults are 3 mS for Port 2 & Port 3 reply delay time
R4042=0003H ; the default is 3 mS for Port 4 reply delay time
- When upgrading the PLC OS firmware version V4.20 or later, it needs version V1.03 of the update utility Os_update.exe for working.