☆☆☆  <u>Updating of FBs OS V4.51</u>          09/27/2007

● Modify the FUN86 instruction -- Reset the output value of the corresponding output
                                    registers of this instruction while it is not executed.
● Modify the FUN30 instruction -- It can have bumpless transfer while the operation
                                    is switched from manual to auto mode at any situation.
                                 -- It can have adaptive output for the PID loop even it
                                    exists the offset of the output ($Bias \neq 0$).
● Support bar-code management for production