☆☆☆ Updating of FBs OS V4.61   11/12/2009

● MA main unit supports full function of hardware high speed counter

● Modify the detection method for RTC chip, and also read/write access

● Modify FUN140/FUN147 motion instructions, it can display the deceleration speed while M1991=1, and quit the pulse output