

《FATEK Communication Server Version1.10 Build6321 Change Note》

1. Adding the range of register(D3072~D4095 & F0~F8191).
2. Remove the bug which 32-bit data can't write into the FBs PLC.