

- **WinProladder V2.41 update explanation**

- **Add “FUN” instruction**

- **New function**

- 1.Can set to connect Ethernet by inputting domain-name ◦

- **Function revision function**

- 1.The revision works as [Connect to PLC], and non-open the associated project file, execute F147 table instruction’s inspection and reconstructing table’s content.
- 2.Updata function of customer ID code inspection ◦

- **Correction**

- 1.The software high speed counter of FBs-MA models can input X4-X15 ◦
- 2.The new English version will be able to show message of NTC6 and B2A1D/B2DA/B4AD ◦
- 3.After V-Short contacts I/P/N won’t cause compile error ◦
- 4.The communication buffer length will match limitation so won’t lead to communication fail ◦