



Updating of FBs OS V4.52

01/30/2008

- Station number 255 of the Modbus communication protocol means the slave ignores the station number identification and executes this command packet if no communication error.
- Improve the communication quality of FUN151 MD 3 instruction for high speed CPU link
- Improve the communication processing for on board analog boards -- FBs-B2A1D, FBs-B2DA,FBs-B4AD