

- **WinProladder V2.44 function updation**

- **New “FUN” instruction**

None

- **New function**

1.Addition the port number's detection of Connect auto check.

- **Function revision**

1.The origin line at right side of coil to show.

2.The parameter of F92&F93 could input HSC2&HSC3.

- **Correction**

1. Revise mistake of “can't print attached drawing & replace F170~F175's parameter”

2. Revise mistake of “different syntax's processing of step instruction by on-line & off-line treatment will lead to next unidentical connection”

3. Revise mistake of “when 2 networks at line 11 & 22 columns, FUN edition will recognize one more row”

4. Revise mistake of “can't print [Cross Reference]”